

Troubleshooting

(Jacobs taper arbor)

| | Details of the trouble | Cause | Pulled out of holder. Unable to attach fast to spindle or holder in case of MT shank. |
|---|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1 | Unable to install or fasten tool. | ① Seized or adhered chip and dust to arbor and tool attachment part. ② Adhered oil to arbor and tool attachment part. ③ Wrong taper size. ④ Scratch and dent in arbor or tool attachment part. | ① Cleaning of arbor and tool attachment part. ② Cleaning (degreasing) of arbor and tool attachment part. ③ Check taper size. ④ • Replacement of arbor or tool • Touching up of area in question (rubbing off with sand paper #1000 and above) Correction (grinding) by NT TOOL is not possible. |
| 2 | Tool is pulled out during use. | ① Seized or adhered chip and dust to arbor and tool attachment part. ② Adhered oil to arbor and tool attachment part. ③ Machining vibration caused by cutting resistance is large. | ① Cleaning of arbor and tool attachment part. ② Cleaning (degreasing) of arbor and tool attachment part. ③ Revision of cutting conditions (Decrease cutting resistance.) a. Higher rotation or lower feed rate (Approx. 20%) |
| 3 | Machining accuracy is not stable. | ① Cutting resistance is too large. ② Mischoice of retention stud ③ Expansion of BT shank because of over-tightening retention stud. ④ Low taper contact of interface • Poor taper contact from expanded spindle nose • Dust, scratch or dent in the taper part or end face (in the case of two-face contact) | ① Revision of cutting conditions (Decrease cutting resistance.) a. Higher rotation or lower feed rate (Approx. 20%) ② Use designated retention stud for the machine. ③ Keep recommended torque value for tightening retention stud. ④ • Regrinding and correction of machine spindle (Contact the manufacturer.) • Cleaning of taper and end face (in the case of two-face contact) , touching up of scratch or dent. |
| 4 | Poor holding accuracy | ① Seized or adhered chip and dust to arbor and tool attachment part. ② Scratch and dent in arbor or tool attachment part. ③ Poor accuracy of tool | ① Cleaning of arbor and tool attachment part. ② • Replacement of arbor or tool • Touching up of area in question (rubbing off with sand paper #1000 and above) Correction (grinding) by NT TOOL is not possible. ③ Replacement of tools. |